



61725913

3. Form Tracking Number

AUTHORISED RELEASE CERTIFICATE EASA FORM 1

LBA / Germany

20862572 00000001

4. Organisation Name and Address:

Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany



5. Work Order/Contract/Invoice

61725913

8. Part No.

9. Qty. 10. Serial No.

11. Status / Work

7. Description

HG2050AC07

REPAIRED

12. Remarks

Aircraft End of Life Solutions BV R20155
ATA 3421 TPR
MK-No. 10 Pack Code 00
Resp. Workshop 33431010
Workshop Station HAM305

Return to Service in Accordance with 14 CFR part 43
The work identified in block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work the items are approved for return to service under

FAA Certificate No. DLAY225D

Opr. Hours Cycle Opr. Day
UNKNOWN UNKNOWN UNKNOWN
TSO UNKNOWN UNKNOWN UNKNOWN
TSC UNKNOWN UNKNOWN UNKNOWN
TSF 0 0 0 0

TASK PERFORMED IN ACCORDANCE WITH CMM 34-26-93
REV. 23 / CMDS 34-26-93 ISSUE 038

13a. Certifies that the items identified above were manufactured in conformity to:

approved design data and are in a condition for safe operation

non-approved design data specified in block 12

Part-145.A.50 Release to Service

Other Regulation specified in block 12
Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part- 145 and in respect to that work the items are considered ready for release to service.

Further details of work performed are attached either in a Workshop Report (reference number: see blocks 3 and 5) or in other applicable documents.

13b. Authorised Signature

13c. Approval / Authorisation Number

14b. Authorised Signature

14c. Certificate / Approval Ref. Number

13d. Name

13e. Date (dd mmm yyyy)

14d. Name

14e. Date (dd mmm yyyy)
17 Jun 2020

Manfred Strauss
Manfred Strauss

DE.145.0001

EASA FORM 1 - Issue 3

USER/INSTALLER RESPONSIBILITIES

Note: This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.


Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

LHT Form 30800 F-20 (HAM TQ/A)



61725913

Workshop Report

Customer Order No. R20155	 Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany		Certificate Ref. No. 20862572 00000001
Part. No. as received HG2050AC07	Serial No. as received 56025774	Work Order/Contract/Invoice 61725913	
Part No. as dispatched HG2050AC07	Serial No. as dispatched 56025774	Description AIR DATA INERTIAL REF. UNIT	
Reason for removal test/inspect		Responsible Workshop 33431010	Modification Status according to Mod-Label
Findings Incoming test failed with present temperature fail. BITE: overheat detection (many times). CCA8: temp detection is faulty, 96deg are indicated instead of 32deg. Scratches on housing without functional meaning.		2	3 4
Action Repl. A8-Card PN 26015513-104, SN out 7030, in 74221774. Rebias. Complete Test performed, o.k.		Name 23391, Manfred Strauss	
The work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not superseded by another agreement or not yet agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder.		Date (dd mmm yyyy) 17 Jun 2020	



Smartlabel-ID: 100000003566869



61725913

Ident-Tag Barcode

Ident-Tag



Lufthansa Technik

Form Tracking Number 20862572 00000001 | Work Order / Contract / Invoice

Description
AIR DATA INERTIAL REF. UNIT

Part. No.
HG2050AC07

Eligibility

Quantity
1

Status / Work
REPAIRED

Serial-/Batch No.
56025774

Remarks

TP R MK-No. 10
FSCM 65507 ATA

Resp. Workshop 33431010 Workshop Station HAM305

Packaging Code: 00 (no deviation allowed)
Instructions:ESD Bag Pink Protection class D

Installed on (Information is only required in case of installation only)

PNR NHA

SNR NHA

Position/FIN No. NHA

Station

A/C-Registration

Removed

PNR¹

SNR¹

Position/FIN No.¹

Station¹

A/C-Registration¹

Unit Barcode No.

Removed from NHA (Information is only required in case of part change on next higher assy)

PNR NHA

SNR NHA

Position/FIN No. NHA

Reason for Removal¹

22 Unscheduled

Complaint No.¹ or WO-Reference¹

11 Scheduled

Failure Description¹ (Please write in capital letters only)

CCI-ID²

Stamp or ID Number + Signature^{1/2}

Date¹

¹ Mandatory entries without using CCI-Mask

² Mandatory entries using CCI-Mask

LHT Form 31794 E-20 (FRA T/FS-QP)

Special Investigation Tag exists Yes

Please send back to:(unless other return location is agreed)

LUFTHANSA TECHNIK AG
c/o Lufthansa Technik Logistik Services GmbH
Warenannahme / Goods Receiving
Weg beim Jaeger 193
22335 HAMBURG-FUHLBUETTEL
Deutschland

(LTLS-Information: Use this box for ZID)