

1. Approving Civil Aviation Authority/Country
Transport Canada

**AUTHORIZED RELEASE CERTIFICATE
 FORM ONE**

2.
 3. Form Tracking Number:
WO125923

4. Organization Name and Address:

AJW Technique Inc
 7055, rue Alexander Fleming
 Saint-Laurent QC H4S-2B7
 Canada



5. Work Order, Contract or Invoice Number:
R22182-2

6. Item: 7. Description:

1	FCD66 MIKII Full Colour Display Unit	8. Part Number: 45606112	9. Quantity: 1.00	10. Serial/Batch Number: 2103	11. Status/Work: REPAIRED
---	--------------------------------------	-----------------------------	----------------------	----------------------------------	------------------------------

12. REMARKS

UNIT REPAIRED AND TESTED SERVICEABLE IN ACCORDANCE WITH CMM 31-63-23A REV.18 DATED MAY 29, 2009.
 FOR ADDITIONAL INFORMATION REFER TO THE TEAR DOWN REPORT.

13a. Certifies the items identified above were manufactured in conformity to:

- Approved design data and are in a condition for safe operation.
- Non-approved design data specified in Block 12

EASA Approval No.: EASA.145.7260
 Maintenance performed in accordance with FAR 43.17

14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations.

- CAR 571.10 Maintenance Release
- Other regulation specified in Block 12

13b. Signature:	13c. Approved Organization Number	14b. Signature	14c. Approval Organization Number
13d. Name (Typed or Printed):	13e. Date	14d. Name (Typed or Printed)	14e. Date (dd/mm/yyyy)
		Stephane Duquette	08/Jul/2022

Installer Responsibilities

This certificate does not constitute authority to install the part.
 Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified.
 Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.

To:
ATTN: Floris Buijs
AIRCRAFT END OF LIFE SOLUTIONS BV
TECHNOLOGY BASE
Vliegveldstraat 100, Hangar 9
7524 PK Enschede
NETHERLANDS

Code: S3B11 **Fax:** +31(0)88-2357001 **Descr:** FCD66 MKII Full Colour Display Unit

Phone: +31(0)88-2357000

Email: repair@aels.nl

P/N: 45606112

S/N: 2103

Mfg: THALES AVIONICS SAS

TSN: UNK **TSO:** UNK **TSR:** UNK **CSN:** UNK **CSO:** 7989 **CSR:** UNK

P/N Out: 45606112 **S/N Out:** 2103

Symptoms:

CODE: REPAIR

DETAILS: PLEASE QUOTE FOR TEST.

Faults:

CODE: OUT OF CALIBRATION

DETAILS: BRIGHTNESS OUT OF SPECIFICATION.

CODE: CLEANING

DETAILS: NEW CALIBRATION REQUIRED PER CMM INSTRUCTIONS.

CODE: DUST IN UNIT.

DETAILS: CLEANING IS REQUIRED.

CODE: REPAIR

DETAILS: The following repair(s) will be performed:

CLEANING.

NEW CALIBRATION REQUIRED.

TEST AND CERTIFICATION.

Corrective Actions:

CODE: REPAIRED

DETAILS: CLEANED UNIT.

REALIGNED AND CALIBRATED UNIT PER CMM INSTRUCTIONS.

UNIT TESTED SERVICEABLE PER CMM 31-63-23A REV.18 DATED MAY 29, 2009.